ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	11	Kuvempu Nagar
Street ID	**Street Name**	**Significant Landmark**
W0633, W0516, W0518, W0520, W0498, W0490, W0627, W	NA, Muniswamy Shetty Lyt Rd, 2nd Crs, 1st Crs, N G E F Industrial Area	Kuvempunagara 2nd Stage
Segment No.	**Total Length (m)**	
11/C-W0633/S011423	719.47	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	56.41	77.541719	13.075061	77.542239	13.075045	W0629	DEAD END
2	60.31	77.541715	13.075286	77.542271	13.075274	W0629	DEAD END
3	62.31	77.541722	13.075444	77.542296	13.075420	W0629	DEAD END
4	83.85	77.540887	13.075284	77.541659	13.075255	W0627	W0629
5	84.26	77.540894	13.075488	77.541663	13.075492	W0627	W0629
6	83.18	77.540908	13.075780	77.541674	13.075731	W0627	W0629
7	85.99	77.540861	13.075003	77.540872	13.075780	W0027	W0490
8	79.88	77.540533	13.072193	77.541240	13.071993	W0633	W0027
9	66.83	77.540612	13.072499	77.541208	13.072345	W0633	W0027
10	56.45	77.540688	13.072805	77.541186	13.072658	W0633	W0027

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements and Asphalting to Roads Kuvempunagara 2nd Stage in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	3000000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements and Asphalting to Roads Kuvempunagara 2nd Stage in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	011-15-000002
Work Order No.	**Work Order Date**	**Period of Extention**
	16/02/2016	90 DAYS

EE/BTP/BBMP/E-PMT/219/2015-16

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
16/02/2016	15/02/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
B B UMESHA		0.00
Phone No.	**E-Mail ID**	
9886213563		

Field Inspection Details

Number of Trees	Any Other Information	Name
15		Suresh
Date of Inspection	**Remarks**	
17/06/2016	completed	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0633, W0516, W0518, W0520,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	18/06/2016	17/07/2016	COMPLETED
SE	VASU K M	18/06/2016	17/07/2016	COMPLETED
EE	YARAPPA REDDY	18/06/2016	17/07/2016	COMPLETED
AEE	SHIVAKUMAR	18/06/2016	17/07/2016	COMPLETED
AE	SURESH	18/06/2016	17/07/2016	COMPLETED
AE	SURESH	17/06/2016	17/07/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0633, W0516, W0518, W0520,